


## Internal

- |    |   |    |   |
|----|---|----|---|
| A. | Asbestos <u>cement</u> Water tank           | H. | <u>AIB</u> behind fuse box  |
| B. | Pipe <u>lagging</u>                         | I. | <u>AIB</u> airing cupboard and/or sprayed insulation coating boiler |
| C. | Loose fill insulation                       | J. | <u>AIB</u> partition wall   |
| D. | <u>Textured decorative coating</u> eg artex | K. | <u>AIB</u> interior window panel                                    |
| E. | <u>AIB</u> ceiling tiles                    | L. | <u>AIB</u> around boiler  |
| F. | <u>AIB</u> bath panel                       | M. | <u>Vinyl</u> floor tiles  |
| G. | <u>Toilet seat and cistern</u>              | N. | <u>AIB</u> behind fire  |



## External

- |    |  |
|----|--|
| O. | Gutters and Asbestos <u>cement</u> downpipes |
| P. | Soffits – AIB or <u>asbestos cement</u>      |
| Q. | <u>AIB</u> exterior window panel             |
| R. | <u>Asbestos cement</u> roof                  |
| S. | <u>Asbestos cement</u> panels                |
| T. | <u>Roofing felt</u>                          |

